

03500.013077.1



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Pat	tent of:)		
ISAO KOBAYASHI ET AL.		:	Examiner: J.P. Mondt Group Art Unit: 2826	
Appln. No.: 09/842,694		:		
Filed: A	April 27, 2001	:		
For:	PHOTOELECTRIC CONVERTER, METHOD FOR DRIVING PHOTOELECTRIC CONVERTER AND SYSTEM HAVING PHOTOELECTRIC CONVERTER	:) :) :)		Certificate JUL 0 6 2005 of Correction
U.S. Patent No.: 6,867,469 B2		:		
Issued:	March 15, 2005	:	June 30, 2005	

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

07/01/2005 SSITHIB1 00000104 6867469

01 FC:1811

100.00 OP

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

John W. Krause

Attorney for Patentees Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY_Main 509104v1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. :

US 6,867,469 B2

DATED

March 15, 2005

INVENTOR(S) :

ISAO KOBAYASHI ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 3:

Line 57, "each" should be deleted.

COLUMN 7:

Line 42, "resulting in" should read --with the result--;

Line 53, "respective" should read --respect--; and

Line 65, "D" (second occurrence) should read --G--.

COLUMN 9:

Line 25, "of" should read --the--.

COLUMN 10:

Line 36, "the" should read --since the--.

COLUMN 12:

Line 34, "can" should read --can be--.

COLUMN 13:

Line 11, "respective" should read --respect--;

Line 21, "of time." should read --time.--; and

Line 45, "thus" should read --the--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_Main 509104v1

PATENT NO. <u>US 6,867,469 B2</u>

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

:

US 6,867,469 B2

DATED

March 15, 2005

INVENTOR(S) :

ISAO KOBAYASHI ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14:

Line 1, "are" should read --is--; and Line 58, "some" should be deleted?

COLUMN 15:

Line 21, "electrode" should read --electrode by--; and

Line 53, "One example" should read -- Examples--.

COLUMN 16:

Line 46, "characteristic" should read --characteristics--.

COLUMN 17:

Line 12, "be" should be deleted;

Line 20, "thus" should read --this--; and

Line 29, "come" should read --comes--.

COLUMN 20:

Line 13, "got" should read --enter--.

COLUMN 21:

Line 16, "While, it has been made clear that" should read --As has been made clear,--; and

Line 54, "both" should read --in both--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_Main 509104v1

PATENT NO. US 6,867,469 B2

No. of add'l. copies @ 30¢ per page

@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. :

US 6,867,469 B2

DATED

March 15, 2005

INVENTOR(S) :

ISAO KOBAYASHI ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23:

Line 38, "mounted" should read --mounted on--; and Line 62, "emit" should read --emits--.

COLUMN 24:

Line 6, "doctors" should read --so that doctors-- and "diagnose" should read --make a diagnosis--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,867,469 B2</u>

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82)

NY_Main 509104v1

Stable Here Ouly!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,867,469 B2

DATED

March 15, 2005

INVENTOR(S) :

ISAO KOBAYASHI ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 3:

Line 57, "each" should be deleted.

COLUMN 7:

Line 42, "resulting in" should read --with the result--;

Line 53, "respective" should read --respect--; and

Line 65, "D" (second occurrence) should read --G--.

COLUMN 9:

Line 25, "of" should read --the--.

COLUMN 10:

Line 36, "the" should read --since the--.

COLUMN 12:

Line 34, "can" should read --can be--.

COLUMN 13:

Line 11, "respective" should read --respect--;

Line 21, "of time." should read --time.--; and

Line 45, "thus" should read --the--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_Main 509104v1

PATENT NO. <u>US 6,867,469 B2</u>

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 6,867,469 B2

DATED

March 15, 2005

INVENTOR(S)

ISAO KOBAYASHI ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14:

Line 1, "are" should read --is--; and Line 58, "some" should be deleted?

COLUMN 15:

Line 21, "electrode" should read --electrode by--; and Line 53, "One example" should read --Examples--.

COLUMN 16:

Line 46, "characteristic" should read --characteristics--.

COLUMN 17:

Line 12, "be" should be deleted;

Line 20, "thus" should read --this--; and

Line 29, "come" should read --comes--.

COLUMN 20:

Line 13, "got" should read --enter--.

COLUMN 21:

Line 16, "While, it has been made clear that" should read --As has been made clear,--; and
Line 54, "both" should read --in both--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 6,867,469 B2</u>

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) NY_Main 509104v1

JUL 0 7 2005

Staple Here Only! WILL SALEN S

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 6,867,469 B2

DATED

March 15, 2005

INVENTOR(S) :

ISAO KOBAYASHI ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23:

Line 38, "mounted" should read --mounted on--; and Line 62, "emit" should read --emits--.

COLUMN 24:

Line 6, "doctors" should read --so that doctors-- and "diagnose" should read --make a diagnosis--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 6,867,469 B2</u>

No. of add'l. copies @ 30¢ per page

